


IMPORTANT NOTES

CASE HARDEN, LEAVE THREADS
SOFT. GRIND AT 'G'. HOLE
MUST BE SMOOTH AND
CONCENTRIC WITH OUTSIDE ALL
UNTOLERANCED DIMENSIONS TO BE
WITHIN ±.008"



SCRAP VIEW SHOWING
 FORM OF ALL UNDERCUTS
 SCALE - 8:1

SECTION THRO' A-A SHOWING
 FORM OF 6 EQUI-SPACED
 SPLINES. SCALE - 2:1

SECTION THRO' B-B
 SHOWING FORM OF 5 EQUI-SPACED
 SPLINES. SCALE - 2:1

GEAR PARTIAL	
No. OF TEETH	= /
D.P.	=
P.A.	=
FORM-STD INV.	

No. PER SET	1
MODELS	BANTAM