




IMPORTANT NOTES

FINISH ALL OVER.

DIMENSIONS ± .010.  
SECTION AA & AA'  
IN POSITIONS AS SHOWN  
PARALLEL TO  
SYMBOL.

SCALE 2:1  
REMOVE ALL BURRS  
TOLERANCES IN  
THOUSANDTHS OF AN INCH  
THICK LINES DENOTE  
MACHINING OR GRINDING  
THREADS TO 'M' TYPE  
TOLERANCES UNLESS  
STATED OTHERWISE

90-352



010 TO 015 CHAMFERS ON THREE  
END FACES OF SPLINES.

